




Cold-working transforms non-magnetic metal into a magnetic hazard.
All that hard work just to become a projectile.