

Inconsistent needle grouping leads directly to needle wobble and poor line stability during application.

The culprit was hiding inside the tip the entire time.