


1. *Thread engagement*
2. *Surface polish*
3. *Edge transitions*
4. *Dimensional consistency*
5. *Machining complexity*
6. *Stone setting*

A professional buyer must check thread engagement, surface polish, and edge transitions.

BUY THE SPECIFICATION, NOT THE ADJECTIVE.