Request exact material batch documentation.

Compare quotes across identical specifications.

Test threads across small initial samples.

Record return rates in stock systems.

3

A listing lead requires thorough due diligence before volume ordering.

Demand verifiable material traceability.