


Check depth of internal thread engagement.

Verify smooth edge transitions under light.

Inspect anodised surfaces for uniform color.

Confirm exact alloy batch certification.

Professional buyers inspect physical tolerances alongside provided paper batch certificates.

Examine every critical wear surface.