- Request exact material compliance paperwork.
- Verify ASTM F138 specifications.
- Check ISO 5832 part 1 standards.
- Inspect finished surface and thread quality.

Standards identify a controlled material supply chain.

Adjectives cannot replace proper batch paperwork.