

Free-machining alloys are cheap to thread but electrochemically leaky due to their inclusions.

The budget metal dissolves far faster than the savings accumulate.