

Polishing removes the passive film and repassivation requires prolonged exposure to air.

Freshly polished metal needs a quiet time out to think about its protective boundaries.