DO NOT MIX NOBLE ENDS.

A LARGE CATHODE DESTROYS THREADS.

SCRATCHED PLATING CREATES ACTIVE CELLS.



KEEP PASSIVE MATERIALS ON BOTH.



DO: USE SAME PASSIVE ALLOY. ✓

A BREACHED SURFACE COATING TURNS COSMETIC JEWELRY INTO AN ACTIVE BATTERY.

STOP MIXING PLATED METALS.