

Physical workflow dictates that clean instruments must never cross back through the dirty zone.
A pristine tool never survives a stroll down the wrong side of the tracks.