


Plating wears and chips to expose the steel substrate and trigger rapid galvanic corrosion.

NEVER COMPROMISE WITH PLATED METALS.