


Budget units suffer voltage drift after ninety minutes of continuous use, impacting physical performance.

VOLTAGE SAG CAUSES INCONSISTENT PENETRATION