


**Avoid coated
threads in
fresh piercings.**

Friction causes failure.

**Choose grown
oxides for high
friction.**

**Friction causes
surface material
wear.**

**DO
NOT
GRIND
COATED
COATED
THREADS!**



**Worn coatings
expose underlying
substrate layers.**

**Internal and external threads grind against each other.
STOP COATING FAILURES BEFORE INSERTION.**