

24.7% of European earrings still exceed the EN 1811 nickel-release limit despite three decades of regulation.

A valiant crusade against sub-par alloys continues.