

Excessive membrane resistance can change the machine's effective hit and reduce needle travel. The trampoline effect was an unexpected feature of the new setup.