


Excessive resistance or lateral movement causes issues that cannot be solved by turning the voltage up.

TECHNICAL DETAILS STUDIOS SHOULD CHECK