




Good initial piercing jewellery is polished to a mirror finish, typically a surface roughness (Ra) below 0.1 micrometres.
It takes longer to calibrate the lasers than to make the jewellery.