




Friction from
daily movement

Worn gold
plating layer

Exposed non-
biocompatible substrate

Weeping piercing channel

Worn gold plating layer

Tissue colour change

Inflamed living tissue

Microns-thick plating inevitably fails from friction and exposes reactive substrates directly to healing tissue.

NEVER SAFE FOR ANY PIERCING