



Step 1 verifies material claims.

Step 2 confirms state statutes.

Step 3 matches inventory records.

Step 4 rejects counterfeit products.

Inspection failures stem from missing material and traceability paperwork.

MAINTAIN STRICT RECORDS