


Two conductors, an electrolyte and a continuous electrical path create galvanic corrosion.

MIXED METALS BUILD A BATTERY