




Clinical scanners operate at up to 60,000 times the strength of the Earth's magnetic field, pulling ferromagnetic metals toward the bore.

# Unverified jewellery is a projectile hazard.