Sterling silver contains highly conductive copper.
The metal is completely non-ferromagnetic.
Conductive loops create severe heating risks.
Remove continuous rings before any scan.



Silver conducts radiofrequency pulses and generates serious localized heat.

REMOVE ALL SILVER RINGS.