

IMPLANT GRADE
TITANIUM IS
INHERENTLY
SAFE.



NIObIUM IS ENTIRELY
NON-FERROMAGNETIC.



POLYMER RETAINERS
CONTAIN ABSOLUTELY
NO METAL.



COLD-WORKED
SURGICAL STEEL
CAUSES **DANGEROUS**
TORQUE.

The radiographer decides which metals remain during the scanning process.
POLYMER RETAINERS GUARANTEE CLEAR SCANS.