



HEAT AND MECHANICAL STRESS CAUSE ULTRAVIOLET STABILIZERS TO DIFFUSE OUT TO THE POLYMER SURFACE.
EXTREME FRICTION OCCASIONALLY GENERATES UNEXPECTED INTERIOR DECORATING.