




Once stabilizers deplete the polymer degrades faster under environmental stress.

A naked structure tends to complain about the weather.