




Chemical additives migrate to the surface and leach into surrounding tissue or fluid under mechanical stress.
BIOCOMPATIBILITY AND MIGRATION OVERVIEW