

Lead in the metal ball was more than 5 times the 0.05% limit.

Bouncing completely over the legal line.