


Undersized autoclaves create pressure to rush cycles and cause incomplete sterilisation.

The laws of physics politely disagree with the packing strategy.