Step A	Chemical inventory and impurity profile.
Step B	Endotoxin limits and heavy-metal screening.
Step C	Validated manufacturing sterility controls.
Step D	Long-term dermal tissue testing.

Multiple components create heavy manufacturing and quality-control burdens.

The safety questions are the product.