

The protective layer on generic steel is vulnerable to chloride ions found in body fluids and sweat.

It was the post-workout sauna that finally broke the chromium oxide's spirit.