
Minimum baseline power units per workstation.



1 artist requires 2 battery packs.

4 daily sessions demand rapid swapping.



Back-to-back scheduling needs 3 units.

Active units require immediate charging backup.

Maintain dedicated wired power reserves always.